

Timeless project



72' (21.9 m) BURGER

LOA:	72' (21.9 m)	Year:	Mfg-1972 Model-1972
Beam:	17'6" (5.3 m)		Refit-2011
Draft:	Min 5' (1.5 m)	Mfg:	BURGER
Speed:	15 knots / 18 knots	Type:	Motor Yacht
Location:	Manitowoc, WI, United States		Classic
		Price:	295,000 USD

Additional Specifications For Timeless project:

LOA:	72' (21.9 m)	Year:	Mfg-1972 Model-1972
Mfg. Length:			Refit-2011
Beam:	17'6" (5.3 m)	Mfg:	BURGER
Draft:	Min 5' (1.5 m)	Model:	Flush Deck Cruiser
Hull Mtrl:	Aluminum	Type:	Motor Yacht
Hull Cnfg.:	Semi-Displacement		Classic
Hull Designer:	Sparkman & Stephens	Top:	With Flybridge
Deck Mtrl:	Aluminum		Bimini Top
Disp:		Speed:	15 knots / 18 knots
Range:		Engines:	2xDetroit Diesel
Int Designer:			12v71
Ext Designer:	Sparkman & Stephens		550 HP
Fuel Cap:	2100 g (7949 l)	Engines Year:	
Water Cap:	500 g (1893 l)	Staterooms:	3
Holding Tank:		Sleeps:	6
Flag:	USA	Heads:	2
Location:	Manitowoc, WI, United States	Crew Quarters:	1
		Crew Berths:	2
		Captain Cabin:	No
		Classifications:	NONE
		Class Type:	
		MCA:	
		ISM:	
		Price:	295,000 USD

72' Burger Overview

Timeless is a classic Burger that was gutted at Burger Boat Company and a full refit started but not completed. All components are stored in heated storage and yacht is ready for a new owner to complete her restoration. Some joinery and electrical work was started. Here is a chance to restore a classic Burger to your specifications. Price reduced!

72' Burger Vessel Walkthrough

Entering the salon through the aft doors, you find a huge salon ready for your personal fit out. The pilothouse will return forward and the dining salon is down three steps and then the galley and then down to the crew quarters. The staterooms are aft down three steps from the dining salon.

72' Burger Accommodations

Once completed, Timeless will offer three guest staterooms aft and a crew quarters forward.

Curtis Stokes & Associates, Inc.

1323 SE 17th Street Suite 168 Fort Lauderdale, Florida 33316 United States
Contact: Curtis Stokes, Phone: +1.954.684.0218, Email: curtis@curtisstokes.net
URL: <http://www.curtisstokes.net/>

Timeless project

11/7/2011

Page 2

The full beam master stateroom is all the way aft with an ensuite head. The two guest staterooms offer side by side berths on one side and over/under berths on the other and share a head.

72' Burger Salon

The huge salon has some joinery and trim fitted and some new wiring run.

72' Burger Galley

The galley is located forward of the dining salon. Any equipment is stored in heated storage.

72' Burger Dining

The dining salon is 3 steps down from the pilothouse.

72' Burger Master Stateroom

The full beam master stateroom is located aft with an ensuite head.

72' Burger Port Guest Stateroom

The port guest stateroom offered twin side by side berths and ensuite head, which has a companionway door for sharing with the starboard guest stateroom.

72' Burger Starboard Guest Stateroom

The starboard guest stateroom offered over/under berths and shares the head with the port guest stateroom.

72' Burger Crew Quarters

The 2 berth crew quarters is located all the way forward with ensuite head.

72' Burger Laundry Room

The washer & dryer was located in the crew quarters.

72' Burger Pilothouse

The pilothouse is flush with the salon and offers side deck access doors on each side.

72' Burger Electronics and Navigational Equipment

Any electronics are stored in heated storage.

72' Burger Electrical System

Some new wiring was run in the refit but not completed.

- 2 X Isuzu 20 kW generators in storage

72' Burger Engine /Mechanical Equipment

2 X Detroit Diesel 12v71 main engines in storage.

72' Burger Deck Equipment

Any deck equipment is stored in heated storage.

72' Burger Hull

Quite a bit of plating has been replaced, as well as struts and thru-hulls. There is a protective coating over the topsides. The superstructure has been protected with thorough covers.

Disclaimer

The Company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change, or withdrawal without notice.

72' Burger pre-refit starboard profile



72' Burger present condition starboard forward profile



Curtis Stokes & Associates, Inc.

1323 SE 17th Street Suite 168 Fort Lauderdale, Florida 33316 United States
Contact: Curtis Stokes, Phone: +1.954.684.0218, Email: curtis@curtisstokes.net
URL: <http://www.curtisstokes.net/>

Timeless project

11/7/2011

Page 5

72' Burger present condition port aft profile



72' Burger present condition starboard aft profile



72' Burger present salon forward



72' Burger present salon aft



72' Burger new salon cabinetry



72' Burger new salon wood panel



72' Burger interior trim in storage



72' Burger present port guest stateroom



72' Burger galley equipment in storage1



72' Burger galley equipment in storage2



72' Burger main engine in storage1



72' Burger main engine in storage2



72' Burger generator in storage1



72' Burger generator in storage2



72' Burger heated parts storage



72' Burger mast in storage



Curtis Stokes & Associates, Inc.

1323 SE 17th Street Suite 168 Fort Lauderdale, Florida 33316 United States
Contact: Curtis Stokes, Phone: +1.954.684.0218, Email: curtis@curtisstokes.net
URL: <http://www.curtisstokes.net/>

Timeless project

11/7/2011

Page 13

72' Burger new hull plating



72' Burger stabilizer fin shaft1



72' Burger new shaft log plating



72' Burger new port shaft bearing housing



72' Burger new port shaft bearing housing2

